

RECEIVED

MAY 12 1986

EPA GW-S
REGION VI

Dec
9/5/15

OSAGE UIC INSPECTION REPORT

- (☒) Initial Inspection
() Follow-up Inspection

Permit No. _____
Inventory No. 4266
Date Inspection 5/1/86
Inspector KY

1. Company/Operator KWB Oil Prop. Mgmt. INC.
2. Business Address 3300 First Nat. Tower Tulsa, OK 74103
3. Individual Contacted NONE, Title _____
4. Lease Name & Well No. (b) (9)
5. Legal Description _____
6. Well Information: SWD ☒ ER _____ Injection Zone _____ Base USDW _____

- Authorized Injection: Pressure _____ psi Rate _____ bbl/d
7. Date of Last Inspection NONE Type ✓
8. Report of Conditions as of this date:
Well Status: Operating _____; through Tubing Yes _____ No _____
Not operating ☒; well equipped Yes ☒ No _____
Well plugged at surface _____ cannot determine _____
Required fittings on Tubing and Casing/Tubing Annulus Yes _____ No ☒
Injection Pressure 0 psi; How Determined line shut-in
Injection Rate 0 BBL/D; How Determined _____
Corrective Actions Completed Yes _____ No _____ Not Determined _____
Records/Files Properly Maintained Yes _____ No _____ Not Determined _____
Samples Taken _____ Photographs Taken _____

Additional Comments and Observations: Well appears inactive. line still connected to well but valve on well is shut-in. line & valve is connected to sledge & cap. No tags. Routine inspection while in area. Well is listed as inactive on well inventory.

9. Corrective Action Required of Operator: NONE

10. The operator is to submit to the Oage UIC office, P.O Box 1495, Pawhuska, OK 74056 by _____ a report with adequate explanation and/or the corrective actions taken. If you desire to contact the field inspector by telephone, you may call (918) 287-4041.

Andrew G. D.
Field Inspector

5/1/86
Date

Given to: _____

Date _____

Mail to: _____

Date _____

across desk
05/09/86 cal

AC